

# SPECIFICATION

Electronic Version 1.2.8

Stylesheet Version 1.0

## ANNULAR FLANGE ON EXTERNAL ROTOR CUP

### Background of Invention

[0001] This invention relates generally to electric motors and more particularly to rotor cups used with electric motors.

[0002] Electric motors that include external rotors are also known as inside out motors, and include magnetic elements mounted on an inner surface of a cup-shaped rotor bell. A stator is located inside a plurality of permanent magnets on the rotor bell. The stator and its supporting structure are shaped to receive a bearing for rotatably mounting a rotor shaft through the stator so that the shaft and rotor bell may rotate relative to the stator. The rotor bell rotates as a result of the magnetic interaction of the permanent magnets and magnetic fields created by energizing windings of the stator.

[0003] During motor operation the rotor spins, and if the weight distribution of the rotor is not balanced, unwanted vibration is induced within the motor. Vibration generates vibratory stresses within various motor components. These stresses degrade operating performance of the motor and reduce its useful life. Therefore, a balanced rotor reduces operational vibration and improves motor life. If a part is press-fit onto the rotor cup, the cup must be supported without allowing forces to be transmitted to the motor bearings. If the cup is not properly supported, the bearings may be damaged, thus reducing product lifetime or increasing audible noise. To facilitate balancing the rotor, various types of balancing rings are added to the rotor cups, and these rings provide a place to add or remove material to achieve the desired rotor balance. The rings constitute additional parts which

increase the process cost of the product.

[0004] Many times magnets are not press-fit into the rotor cup, but rather are fitted to include a gap between the cup and the magnet. The gap is filled with an adhesive. This gap requires additional fixtures to hold the magnet in a desired position concentric to the rotor cup to maintain proper balance. If concentricity is not tightly maintained, balance is sacrificed. At times, the magnet is press-fit into the rotor cup and pushing the magnet into the rotor cup results in the magnet breaking, resulting in higher manufacturing costs.

[0005] When press-fitting components onto a rotor cup, the roundness of a rotor cup is difficult to maintain to a tight tolerance and is often accomplished by making multiple strikes on the part during the forming operation or by increasing the thickness of the material. Increasing material thickness and making multiple strikes increase the product cost.

[0006] It would be desirable to reduce operational vibration and improve the roundness of stamped rotor cups. It would be further desirable for the rotor cup to have a surface for supporting the rotor cup while a load is attached. It would be still further desirable to provide a smooth surface for lead-in when pressing an item, such as a molded permanent magnet, into the rotor cup.

## Summary of Invention

[0007]

In an exemplary embodiment of the invention, an electric motor includes a rotor cup assembly including a rotor cup housing having a unitary annular flange. The rotor cup housing further includes a top, a bottom, a circumferential sidewall and a cavity defined by the sidewall and the top. The annular flange is a ring which extends circumferentially from the rotor cup sidewall. The annular flange increases stiffness of the rotor cup. In addition, the annular flange provides a large surface area that allows the removal or addition of material to dynamically or statically balance the rotor. Furthermore, the annular flange provides a smooth-surface for lead-in when pressing an item, such as a molded permanent magnet, into the rotor cup. The integrated annular flange assists in maintaining the shape of the rotor

cup and results in improving rotor cup balance. As a result, a cost-effective and reliable external rotor cup is provided.

## Brief Description of Drawings

[0008]

[0009] Figure 1 is a perspective view of a known rotor cup.

[0010] Figure 2 is a perspective view of a rotor cup with an annular flange in accordance with one embodiment of the present invention.

[0011] Figure 3 is a perspective view of an inside-out motor including the flanged rotor cup shown in Figure 2.

[0012] Figure 4 is a side view of the motor shown in Figure 3 in a position to be attached to a load.

[0013] Figure 5 is a perspective view of the rotor cup flange shown in Figure 2 in a position to receive a magnet.

## Detailed Description

[0014] Figure 1 is a perspective view of a known rotor cup 10 including a closed end 12, an open end 14, and a sidewall 16 extending between open end 14 and closed end 12. Open end 14 is defined by a lower edge 18 of sidewall 16 and includes a substantially uniform circumferential thickness 20.

[0015] Figure 2 is a perspective view of a rotor cup 22 including an annular flange 24. In one embodiment, flange 24 is unitary with rotor cup 22. Rotor cup 22 further includes a circumferential sidewall 26 having a first diameter 28, a top surface 30, and an open bottom 32. Sidewall 26 has a height 34 measured between top surface 30 and a top edge 36 of annular flange 24. Annular flange 24 is fabricated from the same material as rotor cup 22. In one embodiment, annular flange 24 is fabricated from stamped steel. Annular flange 24 is substantially circular in shape and has an inside diameter 28 and an outside diameter 40. Inside diameter 38 is smaller than outside diameter 40. Annular flange 24 has a height 42 measured

between a bottom edge 44 and top edge 36. In addition, annular flange 24 is outwardly flared from sidewall 26 by an angle  $\phi$  measured between sidewall 26 and bottom edge 44. Angle  $\phi$  permits annular flange 24 to have an outwardly flared curved edge 46 which allows rotor cup 22 to lay flat on a surface (not shown in Figure 2).

[0016] Annular flange 24 increases rotor cup 22 stiffness. In addition, because curved edge 46 is outwardly flared by an angle  $\phi$ , edge 46 provides additional surface area and strength to support rotor cup 22.

[0017] Figure 3 is a perspective view of an inside-out motor 50 including flanged rotor cup 22 shown in Figure 2. Rotor cup 22 includes annular flange 24 and top surface 30. Sidewall 26 extends to top surface 30 so that a top edge 52 is rounded. Inside-out motor 50 further includes a rotor shaft 54, a rotor 56, a stator (not shown), and a frame 58. Rotor shaft 54 is mounted on frame 58 which is attached to the stator such that rotor 56 rotates freely relative to the stator without contacting the stator. In one embodiment, rotor cup 22 is balanced to rotate without vibration. Annular flange 24 permits weights to be attached to flange 24 to achieve a desired level of rotor balance. In another embodiment, material is machined away from flange 24 to achieve a desired level of rotor balance.

[0018] Figure 4 is a side view of inside-out motor 50 shown in Figure 3 positioned to be attached to a load 60. In one embodiment, load 60 is a fan. Inside-out motor annular flange 24 rests on a surface 62 of a tooling apparatus 64 while supporting rotor cup 22. Load 60 is pressed onto rotor cup 22 in a vertical direction 66. Annular flange 24 provides a smooth surface when load 60 is pressed onto rotor cup 22. Annular flange 24 has an increased surface area because of outwardly flared edge 37 (shown in Figure 2).

[0019] Figure 5 is a perspective view of rotor cup 22 including annular flange 24 positioned to receive a magnet 68. Annular flange 24 is configured in a lead-in position to receive circumferential magnet 68. Annular flange 24 is outwardly flared by an angle  $\phi$  and is tapered which assists to guide magnet 68 into rotor cup 22.

[0020] While the invention has been described in terms of various specific embodiments, those skilled in the art will recognize that the invention can be practiced with modification within the spirit and scope of the claims.

100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000